

Product Discontinuation Notice

21 February 2022

Product Discontinuation

Effective immediately rf IDEAS announces the End of Life (EoL) of readers listed in this notice. Suggested replacements for EOL readers are contained in Appendix A.

Acceptance of last-buy purchase requests is based on parts availability. There are finite number of parts available to build several of the readers so when that supply has been consumed the readers requiring those parts will no longer be available.

Replacement Product

The EOL readers listed in Appendix B are in stock. Where possible a suggested replacement has been listed. Please direct any questions to your regional salesperson or our main office to evaluate if a hardware or firmware compatible version is possible.

The readers listed in Appendix C do not have a suggested replacement.

We understand that this announcement may impact your business so please direct any questions to your regional salesperson or our main office.

Reason for EOL

EOL of components and migration to newer readers

Warranty and Technical Support

Warranty on existing and new readers will be honored. Support for firmware changes or modifications have been discontinued. rf IDEAS will continue technical support of existing firmware and all firmware levels are final.

Product Discontinuation Notice

21 February 2022

Appendix A – Product Discontinuation Table

| EOL Model | Suggested Model |
|-----------------|------------------|
| KT-6081AKU | RDR-6081AKU |
| KT-6081APU | RDR-6081APU |
| OEM-805X1AXU-Z | OEM-805X1BXU-Z |
| RDR-60N1AKU-C06 | RDR-805N1AKU-C06 |
| RDR-60N1AKU-C16 | RDR-805N1AKU-C16 |
| RDR-60W1AK6 | RDR-805W1AK6 |
| RDR-60W1AW0 | RDR-805W1AK0 |
| RDR-60W1AW7 | RDR-805W1AK7 |
| RDR-60W1AWE | RDR-805W1AKE |
| RDR-6281APU | RDR-80531BKU |
| RDR-62N1AKU | RDR-805N1AKU |
| RDR-62W1AKU-C06 | RDR-805W1AKU |
| RDR-6381AKU-C06 | RDR-80531BKU-C06 |
| RDR-6382AK2 | RDR-80582AK2 |
| RDR-63W2AKU | RDR-805W2AKU |
| RDR-6681AKU | RDR-80531BKU |
| RDR-6981AKU-C06 | RDR-80531BKU-C06 |
| RDR-69W1AKU | RDR-805W1AKU |
| RDR-69W2AKU | RDR-805W2AKU |
| RDR-6C82AKU | RDR-80532AKU |
| RDR-6D81AKU | RDR-80531AKU |
| RDR-6E81AK7 | RDR-80581AK7 |
| RDR-6E81AKU-C06 | RDR-80531BKU-C06 |
| RDR-6E81AKU-C16 | RDR-80531BKU-C16 |
| RDR-6E81APU | RDR-80581APU |
| RDR-6EW1AK5 | RDR-805W1AK5 |
| RDR-6G81AK2 | RDR-80581AK2 |
| RDR-6H81AK5 | RDR-80581AK5 |

| EOL Model | Suggested Model |
|---------------------|------------------|
| RDR-6H81AK7 | RDR-80581AK7 |
| RDR-6H81AK8 | RDR-80581AK8 |
| RDR-6H82AKU | RDR-80532BKU |
| RDR-6HN1AKU-C06 | RDR-805N1AKU-C06 |
| RDR-6HW1AK2 | RDR-805W1AK2 |
| RDR-6HW1AK5 | RDR-805W1AK5 |
| RDR-6HW1AK7 | RDR-805W1AK7 |
| RDR-6HW1AK8 | RDR-805W1AK8 |
| RDR-6K81AK0 | RDR-80581AK0 |
| RDR-6K81AKU | RDR-80531BKU |
| RDR-6K81AKU-C06 | RDR-80531BKU-C06 |
| RDR-6N81APU | RDR-80531BKU |
| RDR-6NN1AKU | RDR-805N1AKU |
| RDR-6NW1AK2 | RDR-805W1AK2 |
| RDR-6R82AKU | RDR-80532BKU |
| RDR-6T82AKU | RDR-80532BKU |
| RDR-6Z81AKU | RDR-80531BKU |
| RDR-6Z82AKU | RDR-80532BKU |
| RDR-7081BKE | RDR-800W1AKE |
| RDR-7081BKU-ICE0013 | RDR-80081AKU-ICE |
| RDR-7081BKU-ICE0067 | RDR-800H1AKU-ICE |
| RDR-7082BKU-C16 | RDR-80032AKU-C16 |
| RDR-70W1BK0 | RDR-800W1AK0 |
| RDR-70W1BK8 | RDR-800W1AK8 |
| RDR-70W1BKE | RDR-800W1AKE |
| RDR-7L81APU | RDR-7L81AKU |
| RDR-7LH1AKU | RDR-80LH1BKU |
| RDR-80582APU | RDR-80532BKU |

Product Discontinuation Notice

21 February 2022

Appendix B

| EOL Model | Qty | Suggested Model |
|--------------------|-----|-----------------|
| OEM-7021AXU | 8 | |
| OEM-805N1AKU-C36 | 1 | |
| OEM-805N2AKU-02 | 50 | |
| OEM-805X2AXU-Z | 3 | OEM-805X2BXU-Z |
| RDR-30582AKU | 4 | |
| RDR-6081AK5 | 6 | RDR-80581AK5 |
| RDR-6081AKU-G10201 | 8 | |
| RDR-60N2AKU | 3 | RDR-805N1AKU |
| RDR-60W1AWU | 1 | RDR-805W1AKU |
| RDR-6381APU | 14 | RDR-80531BKU |
| RDR-6781AK0 | 1 | RDR-80581AK0 |
| RDR-6981AK0 | 1 | RDR-80581AK0 |
| RDR-6981APU | 2 | RDR-80531BKU |
| RDR-69D2AKU | 6 | |
| RDR-6E81AK0 | 3 | RDR-80581AK0 |
| RDR-6E81AK5 | 1 | RDR-80581AK5 |
| RDR-6EW2AKU | 9 | RDR-805W2AKU |
| RDR-6G81AKU | 1 | RDR-80531BKU |
| RDR-6H81AK2 | 1 | RDR-80581AK2 |
| RDR-6H81AKU | 3 | RDR-80531BKU |
| RDR-6NN1-5 | 5 | |
| RDR-6T81AKU | 5 | RDR-80531BKU |
| RDR-7080AKU-C16 | 4 | |
| RDR-7081AK0 | 1 | RDR-80081AK0 |
| RDR-7081BK7 | 6 | RDR-80081AK7 |

| EOL Model | Qty | Suggested Model |
|-------------------|-----|------------------|
| RDR-7085AK0 | 16 | |
| RDR-7085AKU-590 | 9 | |
| RDR-70W1BK2 | 3 | |
| RDR-70W1BK7 | 2 | RDR-800W1AK7 |
| RDR-70W1BKU | 13 | RDR-800W1AKU |
| RDR-7581AK0-FW810 | 47 | |
| RDR-7581AK5 | 3 | RDR-80581AK5 |
| RDR-7581AK7 | 19 | RDR-80581AK7 |
| RDR-7585AK0 | 3 | |
| RDR-7585AK7-SL | 33 | |
| RDR-75N1AKU | 4 | RDR-805N1AKU |
| RDR-75N1AKU-C06 | 8 | RDR-805N1AKU-C06 |
| RDR-75W1AK5 | 2 | RDR-805W1AK5 |
| RDR-75W1AK7 | 18 | RDR-805W1AK7 |
| RDR-75W2AKU | 24 | RDR-805W2AKU |
| RDR-7F81AKU | 7 | RDR-80FH1AKU |
| RDR-7J81AKU | 1 | |
| RDR-7LW2AKU | 4 | |
| RDR-80582APU | 1 | RDR-80532BKU |
| RDR-805H2AGU | 24 | |
| RDR-805H2AKU | 1 | |
| RDR-805N1-2-WM | 22 | |
| RDR-805N1AK0-C16 | 22 | |
| RDR-805N1AK8 | 2 | |

Product Discontinuation Notice

21 February 2022

Appendix C

| EOL Model | EOL Model | EOL Model | EOL Model |
|---------------------|----------------------|---------------------|---------------------|
| KT-6081AKU-DEMO | RDR-6381AKU-14869 | RDR-70W1BK0-C72 | RDR-805N2AKU-WM-C72 |
| KT-75W5AK8-IP67 | RDR-6381AKU-15024-16 | RDR-7582AKU-CDM | RDR-805W1AK5-029 |
| KT-7L81AKU4 | RDR-6381AKU-15083 | RDR-75D2AKU | RDR-805W1AWB-P |
| KT-800W1AK0-IP67 | RDR-6381AKU-15156 | RDR-75N5AKU | RDR-805W1AWE-P |
| KT-800W1AKE-P-IP67 | RDR-6381AKU-15385 | RDR-75W5AK5 | RDR-805W2AK0-C72 |
| KT-80581AKU-EVAL | RDR-6381AKU-15512 | RDR-7FW1AKU | RDR-805W2AKU-C72 |
| KT-USB-RS232-CAB | RDR-6381AKU-16012 | RDR-7L83AKU-BNP | RDR-83X81AK0-14613 |
| OEM-6022AXU-SSH | RDR-6381AKU-16314 | RDR-7L83AKU-ENKK | RDR-83X81AK2-14613 |
| OEM-7512AXU-SSH | RDR-6381AKU-16918 | RDR-7LN2AKU | RDR-83X81AK2-15024 |
| OEM-805N1AK0 | RDR-6381AKU-17183 | RDR-7LW2AKU | RDR-83X81AK2-15083 |
| OEM-805N1AK5 | RDR-6381AKU-17205 | RDR-7Y81BKU-CB | RDR-83X81AK2-15652 |
| OEM-805N1AKT-02 | RDR-6381AKU-17531 | RDR-80081AKE-P | RDR-83X81AK2-1771X |
| OEM-805N1AKU-C16 | RDR-6381AKU-17620 | RDR-80081AKU-55-006 | RDR-83X81AK5-15083 |
| OEM-805N2AKT-07 | RDR-6381AKU-18481 | RDR-80081APU | RDR-83X81AK5-15652 |
| OEM-805N2AKU-02C | RDR-6381AKU-1852X | RDR-80082AKU-056 | RDR-83X81AK5-16012 |
| RDR-6081AK0-FW810 | RDR-6381AKU-C16 | RDR-800H3AKU | RDR-83X81AK5-17094 |
| RDR-6081AKU-78X-C06 | RDR-6381APU-18538 | RDR-800N1AK5 | RDR-83X81AK5-FD01 |
| RDR-60D1AKU-ED | RDR-6382AKU-15385 | RDR-800N1AKU-WM72 | RDR-83X81AK6-17094 |
| RDR-60N1AK0 | RDR-6382AKU-15652 | RDR-800N2AKU | RDR-83X81AK7-10251 |
| RDR-60N1AK0-C06 | RDR-63D1AKU-11428 | RDR-800W1AK0-C72 | RDR-83X81AK7-15024 |
| RDR-60N1AKU-G10201 | RDR-63W1AKU-10189 | RDR-800W1AK2 | RDR-83X81AK7-15083 |
| RDR-60W1AW2 | RDR-63W1AKU-15652 | RDR-80581APU-C16 | RDR-83X81AKU-10219 |
| RDR-6311AKU-14966 | RDR-6781AKU-5Y | RDR-80582AK0-C06 | RDR-83X81AKU-16039 |
| RDR-6312AKU-11207 | RDR-67D1AKU | RDR-80583AKU | RDR-83X82AKU-17620 |
| RDR-6381AKU-09X-C16 | RDR-6922AKU | RDR-805N1AK0 | RDR-83XH1AKU-15652 |
| RDR-6381AKU-1009X | RDR-6E22AKU | RDR-805N1AK2 | RDR-83XN1AK5-1771X |
| RDR-6381AKU-10103 | RDR-6ED1AKU | RDR-805N1AK6 | RDR-83XW1AK5-10251 |
| RDR-6381AKU-10189 | RDR-6EW1AKU | RDR-805N1AK9 | RDR-83XW1AK5-17094 |
| RDR-6381AKU-11207 | RDR-6ND1AKU | RDR-805N1AKU-16-052 | RDR-8X581AKU-059 |
| RDR-6381AKU-11428 | RDR-7081BKU-I55-007 | RDR-805N1AKU-WM72 | |
| RDR-6381AKU-11711 | RDR-7081BPU-5Y | RDR-805N2AK0-C06 | |
| RDR-6381AKU-11789 | RDR-7082BKU-C06 | RDR-805N2AKU | |